

Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

### 6" (152mm) Temperature Chart Recorder



## Specifications

Alarm Type: Audio/Visual on High/Low Temp Limits Ambient Operating RH Conditions: 0-95% RH non-condensing Ambient Operating Temperature Conditions: 32 to 122F (0 to 50C) Approvals: RoHS, CE Battery Backup: 4AA Battery Back-up. Powers unit for up to 2 days. Battery Life (Avg): 48 Hours (Back-up Only) Calibration Options: N100, N300, N400 Channels: CH1: Temperature Chart Rotation Speed: 24 Hour or 7 Day Dimensions: 3.25 x 7.56 x 7.56 in Display Dimensions Height: 1.18 Display Dimensions Width: 0.59 Display Resolution: 0.1 Degree from -9.9 to 199.9; 1 Degree resolution above 199 and below 9.9 Display Type: LCD Enclosure: Rugged Black ABS Case, Polycarbonate Door, Aluminum Dial IP Rating: 21 Included Accessories: AC Adapter, Red Pen, 9V Battery, Quick Start Guide and 4' Bead-Wire Probe. \*Charts sold separately. Keypad Functions: Power On/Off, Pen Home, Alarm Mounting Options: Free Standing or Wall Mounted Note on Relay Type: Relay does not function while unit is running on only battery power. Power Cord: 6 ft Power Source: 120 to 240 VAC, 12 VDC (INTL fittings available); AC Adapter Power Status Indicator: LED Indicator **Relay Connection:** Spade Lugs, Male 0.25. One Relay per Channel. Relay Type: SPST, 24 VDC, 0.5 A, N/O

#### **Remote Sensor Length:** 4

Remote Sensor Type: 1 K T/C with Mini Connector

**Response Time:** 30 Seconds to 63% of Full Scale

**Temperature Accuracy:** +/-1.8F from -22 to 122F 3.8F Remaining (+/-1C from -30 to 50C 2.1C Remaining) **Temperature Range:** -100 to 0F/C; -50 to 0F/C; -50 to 50F/C; 0 to 50F/C; 0 to 100F/C; 0 to 250F/C; 0 to 500F; 50 to 100F/C

Temperature Sensor: Remote Probe

Unit Weight: 5 lbs

Units/Pkg: 1

Warranty: 12-Month Limited



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

#### Calibrations

N100: 1-Point NIST Traceable Calibration

- N300: 3-Point NIST Traceable Calibration
- N400: 3-Point Ultima NIST A2LA Accredited Calibration

#### Accessories



**A868 - Sensor Dust Filter** Sensor Dust Filter - prolong the life of your sensor.



**R400 - Replaceable Sensor** Single K-TC Replaceable Temperature Sensor



**A062 - AC Adapter Extension Cable** 10' Power Extension for R157 AC Adapter



**R066 - Universal Plug Kit for Data Loggers** International Plug Kit for Data Loggers



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

#### Accessories



**R180 - Replacement AC Adapter** AC Adapter for TSB/TWE/TWP Loggers and the KT8/KT6 series.



**A203 - Temperature Probe** 6" (15cm) High Temperature Immersion Probe



A340 - Glycol Bottle Bottle of Glycol Solution w/ Septum Close



**D118 - Sensaphone Dialer** Remote Monitoring Unit - calls 4 numbers



**D605 - Piercing Probe** 4" (10cm) Thermocouple Handled Piercing Probe



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

#### Accessories



**D611 - Shielded Immersion Probe** 15' (4.5m) Shielded Thermocouple with 4" (10cm) stainless steel tip



**D617 - Probe Extension** K-Thermocouple 10' (3m) Extension Cable



**E200 - 2-Year Warranty** 2-Year Warranty



**A202 - Thermocouple Extension** K-Thermocouple 100' (30m) Extension Cable



**R007 - 9V Battery** 9V Battery



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

#### Accessories



**R013 - Temperature Probe** Replacement Bead Wire Temperature Probe